

DIN F FOR 1 1/4" CABLE WORK INSTRUCTION

Please read them carefully before assembling work,
any liability or responsibility for the results of
improper or unsafe installation practices is disclaimed

1. Tools and Materials

measuring tape(with mm graduations),
cable knife, Open-ended spanners,
screw blade, wrench, brush etc.

2. Components of connector (fig 1)

Nut

Inner conductor

Clamp

Cover Screw

3. Trimming cable (fig 2)

Straighten the end of the cable at 100cm
and remove the jacket at least 50cm with a knife

4. Installation(fig 3 4 5)

a. Install item 3 and item 4 into cable,
and also clip the clamp into ripple groove.
Then cur off over part and keep with flat file.

b. Cleft the foam abd outer conductor
by knife point according to fig4

c. Clear the cable, remove dust and copper bits

d. Put inner conductor into cable as fig5

5. Connect outer body and Nut fig 6

a. Connect Item 1 with cable and keep unmovely

b. Spin item 4 very tightly

